

Spring Diesel Commission

Commissioning of Diesel Engine

1. Remove and replace fuel filters
2. Remove and replace engine pencil zincs
3. Check belts for wear/ tension
4. Check coolant level
5. Clean battery terminals/check electrolyte

6 or 8 Cylinder- \$300.00 plus parts

2, 3, or 4 Cylinder- \$240.00 plus parts

Yamaha Factory Recommended Services

100 Hour Service or 1 Year of use: Four Stroke 4 or 6 cylinder

- | | |
|---------------------------------|-----------------------------------|
| 1. Change fuel filters | 8. Grease all fittings |
| 2. Inspect fuel system | 9. Change Gear oil |
| 3. Throttle link adjustment | 10. Check propeller |
| 4. Idle speed adjustment | 11. Inspect Exhaust water passage |
| 5. Clean or change spark plugs* | 12. Inspect timing belt for wear |
| 6. Inspect trim system | 13. Inspect timing chain tension |
| 7. Inspect engine wiring | 14. Computer analysis |

*As necessary

100 Hour Service or 1 Year of use: 6 cylinder 2 stroke

- | | |
|------------------------------------|--|
| 1. Change fuel filters | 8. Inspect trim system |
| 2. Inspect fuel system | 9. Grease all fittings |
| 3. Throttle link adjustment | 10. Check propeller |
| 4. Idle speed adjustment | 11. Inspect Exhaust water passage |
| 5. Clean or change spark plugs* | 12. Remove and replace oil tank filter |
| 6. Oil tank water drain inspection | 13. Oxygen sensor clean replace |
| 7. Oil pump inspection | 14. Computer analysis |

*As necessary

Yamaha 4/6 Cylinder- \$250.00 plus parts _____

100 Hour Service or 1 Year of use:
Mercury Verado 8 or 6 cylinder

- | | |
|------------------------------------|-----------------------------------|
| 1. Change fuel filters | 7. Oil pump inspection |
| 2. Inspect fuel system | 8. Inspect trim system |
| 3. Throttle link adjustment | 9. Grease all fittings |
| 4. Idle speed adjustment | 10. Check propeller |
| 5. Clean or change spark plugs* | 11. Inspect Exhaust water passage |
| 6. Oil tank water drain inspection | 12. Computer analysis |

*As necessary

Mercury Verado 8/6 Cylinder- \$350.00 plus parts _____

Mercury Factory Recommended Services

100 hour service or 1 year of use:
Mercury V6, V8 5.7/6.2L Engine

1. Retorque the connection of the gimbal ring to the steering shaft
2. Change fuel filters
3. Inspect steering system/lubricate linkages
4. Lubricate engine coupler
5. Inspect the Mercathode system operation
6. Change lower unit oil
7. Change transmission oil
8. Inspect the condition and tension of belts
9. Change Engine oil

Mercuriser V6,V8 5.7/6.2L Engine- \$250.00 plus parts _____

300 hour service or 3 years of use:
Mercuriser V6, V8 5.7/6.2L Engine



1. Check exhaust /cooling system.
2. Inspect manifolds and risers
3. Inspect exhaust hoses for wear
4. Inspect and retorque the engine mounts
5. Check the ignition components for wear
6. Clean flame arrestor
7. Clean crankcase ventilation hoses
8. Replace PVC valves as necessary
9. Check electrical system for loose, damaged, or corroded fasteners
10. Inspect the condition and tension of belts
11. Disassemble and inspect the seawater pump, replace worn parts as necessary
12. Clean the seawater section of the closed cooling system.
13. Clean, inspect and pressure test the cap

Mercuriser V6, V8 5.7/6.2L Engine: \$400.00 plus parts _____

Mercuriser Bravo III Corrosion Inspection

1. Inspect Mercathode grounding system
2. Inspect battery terminals and output
3. Perform out of water Ohm tests
4. Perform in water Ohms tests
5. Check grounding system of boat

Mercuriser Bravo III Inspection \$200.00 _____



Oakdale Yacht

520 Shore Drive
Oakdale, NY 11769
SERVICE (631) 589-1087 Option #2
(631) 589-3015 fax
www.oakdaleyacht.com
E-mail: Service@oakdaleyacht.com
E-mail: Sean@oakdaleyacht.com

2021
Summer Rate Card

MANDATORY Credit Card/Payment Information

- Customer Name: _____
- Home Phone: _____
- Cellular: _____
- Work Phone: _____
- E-mail: _____

VISA MASTERCARD DISCOVER AMEX

- Credit Card Number: _____
- Expiration Date: _____
- Security Code : _____

X _____

(Customer Signature)
3% Fee for Credit Card Purchases

- OPEN ACCOUNT
By checking this box, I understand that the above credit card will be charged for any and all services that will be incurred.

- CASH ACCOUNT
By checking this box, I understand that payment is due in full upon completion of service. I have listed my credit card information above. **In the event I am unable to pay for my summerization at time of completion, the above credit card will be charged for this service.**

X _____

(Customer Signature)

Desired Launch Date: _____

- Boat Make/Model _____
- Length _____ Slip # _____
- Key Location _____



520 SHORE DRIVE · OAKDALE, NY 11769
www.OakdaleYacht.com

2021 Summerization Rates

Mechanic Labor Rates.....\$180.00 per hr.
Electrical Service Tech.....\$180.00 per hr.
Mechanics Assistant.....\$ 80.00 per hr
Estimate Fees* \$150.00 per hr.
** Estimated fees to be applied towards service invoice if Oakdale Yacht performs the work.*

**-STANDARD LABOR CHARGES-
(ALL PARTS ADDITIONAL)**

Oil Changes

- 4 Cylinder Gas Inboard..... \$ 95.00
- 6 Cylinder Gas Inboard..... \$105.00
- 8 Cylinder Gas Inboard..... \$115.00
- 4 Cylinder Gas Outboard \$115.00
- 6 Cylinder Gas Outboard \$150.00
- 8 Cylinder Gas Outboard \$150.00
- 6 Cylinder Verado Outboard \$150.00

Complete Tune-Up Inboard or I/O

**All prices are labor only- Parts additional.
(Includes changing cap, rotator, spark plugs and fuel filter.)*

- 4 Cylinder Gas.....\$180.00
- 6 Cylinder Gas.....\$225.00
- 8 Cylinder Gas Carbureted.....\$250.00
- 8 Cylinder Gas Fuel Injected.....\$275.00

Complete Tune-Up Outboard

- *All prices are labor only- Parts additional.*
- 2 Cylinder.....\$115.00
 - 4 Cylinder.....\$225.00
 - 6 Cylinder EFI Outboard.....\$245.00
 - 4 Cylinder 4 Stroke.....\$250.00
 - 6 Cylinder 4 Stroke.....\$300.00
 - 8 Cylinder 4 Stroke.....\$350.00
 - VST Tank Service.....\$225.00
 - Mercruiser Alpha Waterpump Service \$275.00
 - Outboard Lower Unit Gearcase Service..... \$300.00
 - Gas Inboard Engine Waterpump Service ... \$300.00
 - Engine Coolant Change – Time/Material Yes No

Hauling/Launching Rates – Travel Lift/Fork Lift

- Short Haul..... \$12.50 per ft. _____
- Emergency Haul..... \$40.00 per ft. _____
- Launch \$12.50 per ft. _____
- Haul and Block \$12.50 per ft. _____
- Haul, Block, and Launch \$25.00 per ft. _____

Loading/Offloading Rates

- Load on/Offload from a trailer..... \$12.50 per ft. _____
- Load on/ Offload from a transporter..... \$12.50 per ft. _____

Summer Services

- Summerize Engines – Time/Materials Yes No
- Summerize Fresh water system – Time/Materials Yes No
- Summerize A/C Systems & Head – Time /Materials Yes No
- Change Zincs - Time/Materials Yes No
- Paint Transom Assembly with Antifouling Paint \$100.00 Yes No
- Paint Outdrive.....\$90.00 Yes No
- Recon Prop – Time/Materials Yes No
- Shrink Wrap Removal / Set up Canvas \$50.00 Yes No
- Charge Batteries** \$50.00 Yes No
- Install 24 or 27 Series Size Batteries..... \$50.00 Yes No
- **Customers must have their batteries on their boat 2 weeks prior to their launch date.
- Drive Boat to Slip..... \$100.00

Bottom Painting Rates*

- Boat SizeOne Coat Paint (ablativ)
- Up to 30 ft.....\$16.00 per ft. _____
- 31' to 40'.....\$18.00 per ft. _____
- Over 40'.....\$19.00 per ft. _____

*** A \$15.00 paint supply fee will be applied to every bottom paint job.**
Please note: All Bottom paint must be done by Oakdale Yacht.
Customers can NOT paint their boat in our yards.

Compound is Extra

- Up to 29ft \$2.50 per ft. _____
- 30 ft. and over\$3.50 per ft. _____

Detailing Rates-Hull Only

- Boat Size.....Wax Hull
- Up to 25 ft\$11.75 per ft. _____
- 26' to 33'\$13.75 per ft. _____
- 34' to 44'\$14.75 per ft. _____
- Over 44'\$15.75 per ft. _____

Detailing Rates-Topsides Only

PLEASE CALL THE FOLLOWING DETAILERS
AQUASHINE (631) 235-7535

CUSTOMER NAME: _____

Location of Keys: _____

Launch Date: _____ LENGTH _____

MAKE/MODEL: _____